



Vulcan for Grease Traps


3 Months Test Report

KIYOKAWA Plating Industry in Fukui, Japan

Vulcan has a trouble free design and easy installation. The LED light always blinks dependably as it shows the processing conditions.

I have compared the state of the grease trap before and after installing the Vulcan. Before installation, I noticed strong odors when opening the hole. When I opened the hole one month after the installation, no such odors were present.

As for the cleaning intervals, monthly cleaning may now not be required. The effect and cleaning intervals of Vulcan will require an annual observation, however, I believe the amount of cleaning will be reduced remarkably.




Vulcan installed in the factory kitchen

February 16th - Start situation before Vulcan was installed



March 22nd 1 month with Vulcan



May 18th - 3 months with Vulcan treatment

