

VICENÇ MANENT Dairy

Cardedeu, Barcelona (Spain)

INSTALLATION OF VULCAN IN THE RAW MILK PRODUCTION LINE



The aim of this installation was to minimize lime scale deposits in the stainless steel pipes, which are produced from the milk circulating.

To achieve this aim we installed VULCAN in the pipelines between the pump and the heat pipe, which joins the milking parlour to the storehouse.

